

The following projects were found to be exempt from Section 106 Review pursuant to the HUD Programmatic Agreement

Project Number	Project Location <i>*Address for rehab or demo or new construction</i> <i>*Street name &amp; cross streets for site work</i>	Date of Construction/ Age of Building <i>when building is part of project</i>	Project Description <i>Include summary information about repairs, replacement, reconstruction, new construction, or site work</i>	National Register Status	Reasoning	Adverse Effect Finding	Reasoning
<i>example 1</i>	<i>1 Two Street</i>	<i>1960</i>	<i>rehab: storm doors, gutters, insulation</i>	<i>Listed, eligible, non-eligible</i>		<i>No Effect, No Adverse Effect, Adverse Effect</i>	
	793 E McMillian	1920	Install new laminate glass windows in existing openings. Install two double doors with full light glass panels and transom windows. All windows and doors are missing, boarded up or bricked in	Listed	Peebles Corner NR Historic District	No Adverse Effect	Windows and doors are historically appropriate and are replacing missing elements. No replacement of historic material.